

**MARYLAND HISTORICAL TRUST
DETERMINATION OF ELIGIBILITY FORM**

NR Eligible: yes ☐
no ☐

Property Name: Johns' Mill Workers' House (1) Inventory Number: BA-821
Address: East side of Falls Road, North of Butler City: Butler Zip Code: 21023
County: Baltimore County USGS Topographic Map: Hereford
Owner: _____ Is the property being evaluated a district? ☐ yes
Tax Parcel Number: _____ Tax Map Number: _____ Tax Account ID Number: _____
Project: Butler Stone Quarry Agency: Federal Communications Commission
Site visit by MHT staff: ☒ no ☐ yes Name: _____ Date: _____
Is the property located within a historic district? ☒ yes ☐ no

If the property is within a district District Inventory Number: BA2214
NR-listed district ☒ yes Eligible district ☐ yes Name of District: Western Run - Belfast Road
Preparer's Recommendation: Contributing resource ☒ yes ☐ no Non-contributing but eligible in another context ☐ yes

If the property is not within a district (or the property is a district) Preparer's Recommendation: Eligible ☒ yes ☐ no

Criteria: ☐ A ☐ B ☒ C ☐ D Considerations: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G ☐ None

Documentation on the property/district is presented in:
Maryland Historical Trust Library, Crownsville, Maryland

Description of Property and Eligibility Determination: *(Use continuation sheet if necessary and attach map and photo)*

Johns' Mill Workers' House was most recently observed and photographed in February, 2003. Its condition was largely unchanged since the preparation of the State Historic Sites Inventory Form in the library of the Maryland Historical Trust, dated September, 1976.

The property is described in the following documents located at the Maryland Historical Trust Library:

Maryland Historical Trust State Historic Sites Inventory Form, by Beverly W. Young and James T. Wollon, Jr., September 1976.

The following observations were made during the visit to the property:

This simple stone dwelling continues to contribute as a resource of the Butler community. It is associated with the nearby Johns Grist Mill. The shed-roofed addition of the stone house has not been well-maintained; nevertheless, the character and integrity of the original design qualify the property for registration under Criterion C: Design/Construction.

MARYLAND HISTORICAL TRUST REVIEW

Eligibility recommended ☒ Eligibility not recommended ☐
Criteria: ☒ A ☐ B ☒ C ☐ D Considerations: ☒ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G ☐ None
MHT Comments: Contributes to NRHD

Janet Young
Reviewer, Office of Preservation Services

E. Kuntz
Reviewer, NR Program

6/11/03
Date

6/20/03
Date

NR-ELIGIBILITY REVIEW FORM


Johns' Mill Workers' House

Inventory Number: BA-821

Page 2

Prepared by: William C. Riggs, RA

Date Prepared: 5/19/2003



SITE VICINITY MAP

Hereford Quadrangle, MD
(Dated 1991)
SCALE: As Shown



Determination of Eligibility

Johns' Mill Workers' House (BA-821)
Falls Road
Butler, Baltimore Co., Maryland 21023



JOHN'S MILL WORKERS HOUSE

BA-821

BALTIMORE CO., MD

PROSPERITY ST. E. N. 1/4

2/03

NOVEMBER 1902

John's Mill Workers House BA-821

Butler, MD 21136

02-03



**MARYLAND HISTORICAL TRUST
DETERMINATION OF ELIGIBILITY FORM**

NR Eligible: yes ☐
no ☐

Property Name: Johns' Mill Workers' House (2) Inventory Number: BA-822
Address: East side of Falls Road, North of Butler City: Butler Zip Code: 21023
County: Baltimore County USGS Topographic Map: Hereford
Owner: _____ Is the property being evaluated a district? ☐ yes
Tax Parcel Number: _____ Tax Map Number: _____ Tax Account ID Number: _____
Project: Butler Stone Quarry Agency: Federal Communications Commission
Site visit by MHT staff: ☒ no ☐ yes Name: _____ Date: _____
Is the property located within a historic district? ☒ yes ☐ no

If the property is within a district District Inventory Number: BA-2214
NR-listed district ☒ yes Eligible district ☐ yes Name of District: Western Run - Belfast Road
Preparer's Recommendation: Contributing resource ☒ yes ☐ no Non-contributing but eligible in another context ☐ yes

If the property is not within a district (or the property is a district) Preparer's Recommendation: Eligible ☒ yes ☐ no

Criteria: ☐ A ☐ B ☒ C ☐ D Considerations: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G ☐ None

Documentation on the property/district is presented in:
Maryland Historical Trust Library, Crownsville, Maryland

Description of Property and Eligibility Determination: *(Use continuation sheet if necessary and attach map and photo)*
Johns' Mill Workers' House (2) was most recently observed and photographed in February, 2003. Its condition was (un??)changed since the preparation of the State Historic Sites Inventory Form in the library of the Maryland Historical Trust.

The property is described in the following documents located at the Maryland Historical Trust Library:

Maryland Historical Trust State Historic Sites Inventory Form, by Beverly W. Young and James T. Wollon, Jr., September 1976.

The following observations were made during the visit to the property:
Photography of the dwelling was not permitted. The house is similar to Jophns Mill Worker's House (1) (BA-821) and is considered eligible for registration under Criterion C: Design/Construction.


Prepared by: William C. Riggs, RA Date Prepared: 5/19/2003

MARYLAND HISTORICAL TRUST REVIEW

Eligibility recommended ☒ Eligibility not recommended ☐
Criteria: ☒ A ☐ B ☒ C ☐ D Considerations: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G ☐ None

MHT Comments

lacks photo documentation which would enable assessment of current integrity - consider contributing to NRHD for purpose of the current project
James Lewis Tully
Reviewer, Office of Preservation Services
B. Kuntze
Reviewer, NR Program
Date *6/20/03*
Date *6/20/03*



SITE VICINITY MAP

Hereford Quadrangle, MD
(Dated 1991)
SCALE: As Shown



Determination of Eligibility
Johns' Mill Workers' House (2) (BA-822)
Falls Road
Butler, Baltimore Co., Maryland 21023



JOHN'S MILL WORKER'S HOUSE

DA-822

BALTIMORE CO., MD

PR. 21 J. SMITH

2/1/7

ALBANY CO. MD SPPD

John's Mill Worker's House

Butler, MD 21136

BA-822

02-03

CAPSULE SUMMARY

BA- 822

Johns Mill Worker's House #2

15113 Falls Road

Butler, Baltimore County

1870 ca.

Private

Although historic atlases do not support a circa 1870 date of construction for the Johns Mill Worker's House #2, architectural evidence suggests that the dwelling, which is representative of vernacular stone houses constructed throughout Baltimore County in the mid- to late 19th century, does date to the 1870s. An interior architectural survey of the house accompanied by deed research would help to confirm a more exact date of construction. Vernacular buildings tend to have little to no stylistic detailing and are typically constructed by local builders with locally available tools and materials. Vernacular architecture accounts for the majority of the built environment and reflects the traditions of society, rather than the whims of the architect. Throughout Baltimore County, there are a number of vernacular stone houses from this period. Stone was readily available in the county, with both marble and granite quarries located throughout the region. Commonly, these random rubble stone dwellings are two stories in height, single-pile with side gable roofs. This continuity of form is a result of folk architecture and the reliance on constructing forms that had been built by the previous generation. Although the dwelling was devastated by fire in 1950, the building was later renovated and continues to serve as a private residence.

John's Mill Worker's House #2 is a two-story dwelling of solid random rubble stone construction with a side gable roof clad in standing seam metal and one reconstructed central interior stretcher bond brick chimney. Circa 1980, the house experienced a phase of renovations that resulted in the construction of a two-story wood frame ell clad in board-and-batten siding and the presence of a one-story façade porch enclosed with board-and-batten siding below a shed roof. The building fronts south and sits in a meadow on the east side of Falls Road and is accessible by a long, winding gravel driveway. The façade is pierced by an offset one-light single-leaf wood door that dates to circa 1970. Two 1/1 windows flank the entry. Two 6/6 windows pierce the second story of the façade. Board-and-batten siding covers the gable peaks of the main block. The ell is two bays deep and encircled by a wood deck at the second story that connects the house to the ice house, which is sited to the north. The circa 1870 ice house was also extensively renovated circa 1970. The building presently features a solid random rubble stone foundation and a wood frame second story that is clad in board-and-batten siding with a front gable roof clad in standing seam metal. The foundation, which is banked into the hillside, is pierced by one flush-vertical-board single-leaf door. One historic privy, which dates to circa 1930, is also located on the property. The circa 1980 privy is also one story tall and one bay square.

Maryland Historical Trust

Maryland Inventory of Historic Properties Form

Inventory No. BA-822

1. Name of Property

(indicate preferred name)

historic

other John's Mill Worker's House #2

2. Location

street and number 15113 Falls Road not for publication

city, town Butler vicinity

county Baltimore County

3. Owner of Property

(give names and mailing addresses of all owners)

name Michael R. Cranfield

street and number Druid Hill Park telephone Not Available

city, town Baltimore state MD zip code 21217

4. Location of Legal Description

courthouse, registry of deeds, etc. Baltimore County Courthouse liber 8901 folio 751

city, town Towson tax map 33 tax parcel 19 tax ID number 0501033080

5. Primary Location of Additional Data

- ☐ Contributing Resource in National Register District
☐ Contributing Resource in Local Historic District
☐ Determined Eligible for the National Register/Maryland Register
☐ Determined Ineligible for the National Register/Maryland Register
☐ Recorded by HABS/HAER
☐ Historic Structure Report or Research Report at MHT
☐ Other: _____

6. Classification

Category	Ownership	Current Function	Resource Count
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> agriculture	Contributing
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> commerce/trade	Noncontributing
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> defense	<input type="checkbox"/> buildings
<input type="checkbox"/> site		<input checked="" type="checkbox"/> domestic	<input type="checkbox"/> sites
<input type="checkbox"/> object		<input type="checkbox"/> education	<input type="checkbox"/> structures
		<input type="checkbox"/> funerary	<input type="checkbox"/> objects
		<input type="checkbox"/> government	<input type="checkbox"/> Total
		<input type="checkbox"/> health care	
		<input type="checkbox"/> industry	
		<input type="checkbox"/> landscape	
		<input type="checkbox"/> recreation/culture	
		<input type="checkbox"/> religion	
		<input type="checkbox"/> social	
		<input type="checkbox"/> transportation	
		<input type="checkbox"/> work in progress	
		<input type="checkbox"/> unknown	
		<input type="checkbox"/> vacant/not in use	
		<input type="checkbox"/> other:	
			Number of Contributing Resources previously listed in the Inventory
			1

7. Description

Inventory No. BA- 822

Condition

<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated
<input type="checkbox"/> good	<input type="checkbox"/> ruins
<input checked="" type="checkbox"/> fair	<input type="checkbox"/> altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

Constructed circa 1870, John's Mill Worker's House #2 is a two-story vernacular dwelling of solid random rubble stone construction with a side gable roof clad in standing seam metal and one reconstructed central interior stretcher bond brick chimney. Circa 1980, the house experienced a phase of renovations that resulted in the construction of a two-story wood frame ell clad in board-and-batten siding and the presence of a one-story façade porch enclosed with board-and-batten siding below a shed roof. The building fronts south and sits in a meadow on the east side of Falls Road and is accessible by a long, winding gravel driveway. The façade is pierced by an offset one-light single-leaf wood door that dates to circa 1970. Two 1/1 windows flank the entry. Two 6/6 windows pierce the second story of the façade. Board-and-batten siding covers the gable peaks of the main block. The ell is two bays deep and encircled by a wood deck at the second story that connects the house to the ice house, which is sited to the north.

The circa 1870 ice house was also extensively renovated circa 1970. The building presently features a solid random rubble stone foundation and a wood frame second story that is clad in board-and-batten siding with a front gable roof clad in standing seam metal. The foundation, which is banked into the hillside, is pierced by one flush-vertical-board single-leaf door. The second story, which is accessible by the wood deck extending from the house, features a fifteen-light single-leaf wood door.

One historic privy, which dates to circa 1930, is also located on the property. The one-story, one-bay-square solid concrete block building features a front gable roof clad in standing seam metal and an offset beaded-vertical-board single-leaf door.

The circa 1980 privy is also one story tall and one bay square. The building features a shed roof clad in corrugated sheet metal and a plywood-clad wood frame structural system.

8. Significance

Inventory No. BA- 822

Period	Areas of Significance	Check and justify below			
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> health/medicine	<input type="checkbox"/> performing arts	
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> archeology	<input type="checkbox"/> education	<input type="checkbox"/> industry	<input type="checkbox"/> philosophy	
<input checked="" type="checkbox"/> 1800-1899	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> engineering	<input type="checkbox"/> invention	<input type="checkbox"/> politics/government	
<input checked="" type="checkbox"/> 1900-1999	<input type="checkbox"/> art	<input type="checkbox"/> entertainment/ recreation	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion	
<input type="checkbox"/> 2000-	<input type="checkbox"/> commerce	<input type="checkbox"/> ethnic heritage	<input type="checkbox"/> law	<input type="checkbox"/> science	
	<input type="checkbox"/> communications	<input type="checkbox"/> exploration/ settlement	<input type="checkbox"/> literature	<input type="checkbox"/> social history	
	<input type="checkbox"/> community planning		<input type="checkbox"/> maritime history	<input type="checkbox"/> transportation	
	<input type="checkbox"/> conservation		<input type="checkbox"/> military	<input type="checkbox"/> other:	

Specific dates 1870 ca.-present **Architect/Builder** Unknown

Construction dates 1870 ca., 1970 ca.

Evaluation for:

☐ National Register ☐ Maryland Register ☒ not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

Although historic atlases do not support a circa 1870 date of construction for the Johns Mill Worker's House #2, architectural evidence suggests that the dwelling, which is representative of vernacular stone houses constructed throughout Baltimore County in the mid- to late 19th century, does date to the 1870s. An interior architectural survey of the house accompanied by deed research would help to confirm a more exact date of construction. Vernacular buildings tend to have little to no stylistic detailing and are typically constructed by local builders with locally available tools and materials. Vernacular architecture accounts for the majority of the built environment and reflects the traditions of society, rather than the whims of the architect.¹ Throughout Baltimore County, there are a number of vernacular stone houses from this period. Stone was readily available in the county, with both marble and granite quarries located throughout the region. Commonly, these random rubble stone dwellings are two stories in height, single-pile with side gable roofs. This continuity of form is a result of folk architecture and the reliance on constructing forms that had been built by the previous generation. Although the dwelling was devastated by fire in 1950, the building was later renovated and continues to serve as a private residence.

¹ Dell Upton and John Michael Vlach, editors, *Common Places: Readings in American Vernacular Architecture*, (Athens, GA: The University of Georgia Press, 1986), pp. xv-xvi.

9. Major Bibliographical References

Inventory No. BA- 1822

- Atlas of Baltimore County, Maryland.* Philadelphia, PA: G. M. Hopkins, 1877.
Baltimore County Historic Inventory.
Brooks, Neal A. and Eric G. Rockel. *A History of Baltimore County.* Towson, MD: Friends of the Towson Library, Inc., 1979.
Map of Baltimore County. Philadelphia, PA: G. W. Bromley, 1915.
Scharf, J. Thomas. *History of Baltimore City and County From the Earliest Period to the Present Day: Including Biographical Sketches of Their Representative Men.* Philadelphia, PA: Louis H. Everts, 1881. Reprinted by Higginson Book Company, Salem, MA.
Sidney, J. C. *Map of the City and County of Baltimore, Maryland, from Original Surveys.* Baltimore, MD: James M. Stephens, 1850.

10. Geographical Data

Acreage of surveyed property .50 Acre
Acreage of historical setting Unknown
Quadrangle name Hereford Quadrangle scale: 1:24,000

Verbal boundary description and justification

Since its construction circa 1870, John's Mill Worker's House #2 has been associated with the 6.36 acres of land known as tax parcel 19 of map 33 located in the Baltimore County Tax Assessor's office.

11. Form Prepared by

name/title	A. McDonald and A. Didden, Architectural Historians		
organization	EHT Tracerics, Incorporated	date	May 29, 2001
street & number	1121 5th Street NW	telephone	202.393.1199
city or town	Washington	state	DC


The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
DHCD/DHCP
100 Community Place
Crownsville, MD 21032-2023
410-514-7600

BA- 1822
15113 FALLS ROAD
BUTLER
BALTIMORE COUNTY

USGS Quad: **HEREFORD**
Scale: 1:24,000





BA-1 822

15113 FALLS ROAD, BUTLER

BALTIMORE COUNTY, MD

TRACERIES

4/2001

MD SHOP

SW CORNER

1 of 5



BA-822

15113 FALLS ROAD, BUTLER
BALTIMORE COUNTY, MD

TRACERIES

4/2001

MD SHPO

NW CORNER

2 of 5



BA-0822

15113 FALLS ROAD, BUTLER

BALTIMORE COUNTY, MD


TRACERIES

4/20/11

MD SHPO

ICE HOUSE

3 of 5



BA-0822

15113 FALLS ROAD, BUTLER

BALTIMORE COUNTY, MD

TRACERIES

4/2001

MP SHPO

PRIVY

4085



BA- 822

15113 FALLS ROAD, BUTLER
BALTIMORE COUNTY, MD

TRACERIES

4/2001

MD SHPO

PRIVY

5045

BA-821, 822

Johns' Mill Workers' Houses
East side of Falls Rd. north of Butler
Not accessible
Circa 1812

These two small but substantial dwellings were probably related to the rural industries in this agricultural community. They were part of the property of the Johns family who operated the grist mill just north of here from the early 1800's. The westerly house is very traditional in form and detail and of especially good workmanship and design. It bears a datestone which is nearly illegible but appears to read: 1812, which is an acceptable date, architecturally for both buildings.

MARYLAND HISTORICAL TRUST

BA-821,822

MAG#0308215304
#0308225304

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

Johns' Mill Workers' Houses

AND/OR COMMON

2 LOCATION

STREET & NUMBER

East side of Falls Road north of Butler

CITY, TOWN

Butler

VICINITY OF

CONGRESSIONAL DISTRICT

5

STATE

Maryland

COUNTY

Baltimore

3 CLASSIFICATION

CATEGORY

☐ DISTRICT
☒ BUILDING(S)
☐ STRUCTURE
☐ SITE
☐ OBJECT

OWNERSHIP

☐ PUBLIC
☒ PRIVATE
☐ BOTH

PUBLIC ACQUISITION

☐ IN PROCESS
☐ BEING CONSIDERED

STATUS

☒ OCCUPIED
☐ UNOCCUPIED
☐ WORK IN PROGRESS
ACCESSIBLE
☐ YES: RESTRICTED
☐ YES: UNRESTRICTED
☒ NO

PRESENT USE

☐ AGRICULTURE
☐ COMMERCIAL
☐ EDUCATIONAL
☐ ENTERTAINMENT
☐ GOVERNMENT
☐ INDUSTRIAL
☐ MILITARY
☐ MUSEUM
☐ PARK
☒ PRIVATE RESIDENCE
☐ RELIGIOUS
☐ SCIENTIFIC
☐ TRANSPORTATION
☐ OTHER:

4 OWNER OF PROPERTY

NAME

Anne A. Fogarty and Jane A. Pearce

Telephone #: 472-4151

STREET & NUMBER

Falls Road

CITY, TOWN

Butler

VICINITY OF

STATE, zip code

Maryland 21023

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Baltimore County Courthouse

STREET & NUMBER

Washington Avenue

CITY, TOWN

Towson

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

None

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

PERIOD

AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW

<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input checked="" type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES Unknown

BUILDER/ARCHITECT Unknown

STATEMENT OF SIGNIFICANCE

These two small stone houses appear to have been built as part of the Johns family mill operation at Black Rock Farm. Richard Johns purchased the mill site and surrounding land in 1794 from the widow of Thomas Matthews. A new mill was erected by his son, Kensey Johns, in 1800 and several dwellings, mill buildings and a blacksmith shop were added through the years.

In 1873, Shadrach Kemp purchased the 867 acres comprising parts of Miller's Delight, Mount Airy, Hare's Level and Cables' (or Caples') Habitation. Following Kemp's death in 1884, part of the property was sold to Joseph Royston. In 1912, Royston's heirs sold this parcel to Peter K. Fowble whose heirs continue to occupy the houses.

CONTINUE ON SEPARATE SHEET IF NECESSARY

Continuation Sheet #1

Question #7 continued

The easterly of the two Houses is of stone, two storeys in height, three bays in length, with a low-pitched gabled roof; fire gutted this dwelling ca. 1955. The principal entrance is centered on the south side and a 6/6 window is in either flanking bay; the center bay is void of openings in the second storey. A shed-roofed porch shelters the first storey of the south side. A secondary entrance is centered in the west end. Earlier (than the fire) window frames remain in first storey openings, consisting of narrow beaded material. Gables are of vertical boards, probably the result of earlier stone gables being destroyed in the fire.

The interior of this house was not examined.

In a low hillside immediately north of the house is a stone-walled root cellar, its depth approximately three times its face width.

BA-821, 822

Johns' Mill Workers' Houses
Valleys Historical District

Continuation Sheet #2

Question #9 continued

Hopkins, G.M. Atlas of Baltimore County, Maryland. (Philadelphia, 1877).

Sidney, J.C. Map of the City and County of Baltimore, Maryland. (Baltimore, 1850).